CINELR 7 碳板机架组装说明书

CINELR 7 Frame Assembly Guide



1 组装说明:

Part One



包装里有:

Packing list

1	顶板 Top plate	X1	22	M3*10mm半圆头螺丝 M3*10mm half round head screws	X14
2	中板 Upper plate	X1	23	M3*8mm半圆头螺丝 M3*8mm half round head screws	X14
3	夹板 Mid-lower plate	X1	24	M2.5*6mm半圆头螺丝 M2.5*6mm half round head screws	X3
4	底板 Bottom plate	X1	25	M2*5mm半圆头螺丝 M2*5mm half round head screws	X10
5	机臂A ArmA	X2	26	M2*4mm半圆头螺丝 M2*4mm half round head screws	X3
6	机臂B ArmB	X2	27	M2*5mm半圆头自攻螺丝 M2*5mm pan head self-tapping screw	X3
7	铝合金侧板 CNC camera side plate	X2	28	XT60EW-M 公头 XT60EW-M battery plug	X1
8	侧板PLA打印件 Side panels with LED	X2	29	格纹硅胶电池防滑垫 Battery pad	X2
9	图传天线座TPU打印件 Antenna mount TPU	X1	30	10*10mm集线管 10*10mm Motor wire shield tube	X4
10	接收机座TPU打印件 Receiver mount TPU	X1	31	50*10mm集线管 50*10mm Motor wire shield tube	X4
11	狗座底座TPU打印件 GoPro bottom stand TPU	X1	32	底座LED灯 Base mount LED	X1
12	脚垫TPU打印件 Arm guard TPU	X4		**(附赠)/(Additional parts)**	
13	前保护杠TPU打印件 Front bumpers TPU	X2	33	LED导光条 LED light strap	X4
14	LED灯显LOGO打印件 LED logo TPU	X1	34	20*300mm超纤皮电池扎带 20*300mm Battery strap	X2
15	硅胶侧板 Silicone camera side plate	X2	35	套机通用贴纸V4 Sticker V4	X1
16	M3*30圆形网纹铝柱 M3*30mm standoff	X3	36	内六角扳手 Allen wrench	X1
17	M3*21圆形网纹铝柱 M3*21mm standoff	X3	37	M5防松螺母 M5 screw nut	X1
18	M3 防松自紧螺母 M3 screw nut	X5	38	M5*20mm平头螺丝 M5*20 hex screw	X1
19	M3*30mm半圆头螺丝 M3*30mm half round head screws	X5	39	转接线 IPEX to RP-SMA F Adapter Cable 22CM	X2
20	M3*16mm半圆头螺丝 M3*16mm half round head screws	X5	40	3P双头端子线 3 pin terminal connector	X1
21	M3*12mm半圆头螺丝 M3*12mm half round head screws	X7	41	硅胶线 Power cable	X2

2 组装说明 ：
Part Two



3 组装说明 ：
Part Three



4 组装说明 ：
Part Four



5 组装说明 ：
Part Five