

# XL10 V6

## 机架组装示意图

## Frame Assembly Guide

1. 顶板 Top plate	x1	26. M2*8 内六角带垫螺丝 M2*8 wash head hex screw	x2
2. 中板 Counter plate	x1	27. M2*8 内六角自攻螺丝 M2*8 self-tapping hex screw	x4
3. 机臂A ArmA	x2	28. M3*7 内六角螺丝 M3*7 hex screw	x8
4. 机臂B ArmB	x2	29. M3*14 内六角螺丝 M3*14 hex screw	x4
5. 底板 Bottom plate	x1	30. M3*16 内六角螺丝 M3*16 hex screw	x4
6. 摄像头侧板CNC CNC camera side plate	x1	31. M2*6 内六角沉头螺丝 M2*6 countersunk hex screw	x2
7. 脚垫打印件 Arm guard TPU	x4	32. M3*10 内六角带垫螺丝 M3*10 wash head hex screw	x4
8. GPS座打印件 GPS mount TPU	x1	33. M3*30 内六角螺丝 M3*30 wash screw	x4
9. 可调节狗座底座打印件 GoPro bottom stand TPU	x1	34. 格纹硅胶电池防滑垫 Battery pad	x1
10. 摄像头硅胶侧板 Silicone camera side plate	x1	(附赠)/(Additional parts)	
11. 图传天线座打印件 Antenna TPU	x1		
12. BB响/蜂鸣器打印件 Buzzer holder TPU	x1		
13. 接收机座打印件 Receiver mount TPU	x1		
14. 电源线+XT60E-M 插头 XT60E-M power cable	x1		
15. 固定XT60插头 Integrated XT60 battery plug mount	x1		
16. 9*5.4*6 双通尼龙柱 9*5.4*6 Double-pass Al. standoff	x2		
17. M3*20 圆形网纹铝柱 M3*20 Al. standoff	x4	1. 集线管 Motor wire protector	x4
18. M3*29 圆形网纹铝柱 M3*29 Al. standoff	x2	2. 20*300超纤皮电池扎带 20*300 Battery strap	x2
19. M2*25 圆形网纹铝柱 M2*25 Al. standoff	x1	3. M5螺母 M5 nut	x1
20. M3*12 内六角螺丝 M3*12 hex screw	x16	4. 内六角扳手 Allen wrench	x1
21. M2*6 内六角螺丝 M2*6 hex screw	x2	5. M5*20 内六角螺丝 M5*20 hex screw	x1
22. M3 防松自紧螺母 M3 lock nut	x4	6. 通用贴纸V3 Sticker V3	x1
23. M1.6*16 杯头内六角螺丝 M1.6*16 socket head cap	x4	7. IPEX转SMA直头内针转接线 总长10CM IPEX to SMA adapter cable 10mm	x1
24. M2*12 内六角自攻螺丝 M2*12 self-tapping hex screw	x2		
25. M2*8 内六角螺丝 M2*8 hex screw	x2		

