

AOS 3.5 V5

机架组装示意图

Frame Assembly Guide

- | | |
|-----------------------------|-----|
| 1. 顶板 | x1 |
| Top plate | |
| 2. 底板 | x1 |
| Bottom plate | |
| 3. 机臂 | x4 |
| Arm | |
| 4. 中板 | x1 |
| Counter plate | |
| 5. O3 摄像头固定侧板 | x2 |
| O3 camera side plate | |
| 6. CNC 摄像头侧板 | x2 |
| CNC camera side plate | |
| 7. 脚垫打印件 | x4 |
| Arm guard TPU | |
| 8. 图传天线座打印件 | x1 |
| Antenna TPU | |
| 9. 接收机座打印件 | x1 |
| Receiver mount TPU | |
| 10. 固定XT30打印件 | x1 |
| XT30 upper mount TPU | |
| 11. 摄像头硅胶侧板 | x2 |
| Silicone camera side plate | |
| 12. M2*23 圆形网纹铝柱 | x2 |
| M2*23 Al. standoff | |
| 13. M2*20 圆形网纹铝柱 | x7 |
| M2*20 Al. standoffv | |
| 14. M2*6 内六角螺丝 | x12 |
| M2*6 hex screw | |
| 15. M2*6 沉头内六角螺丝 | x8 |
| M2*6 countersunk hex screw | |
| 16. M2*7 内六角螺丝 | x22 |
| M2*7 hex screw | |
| 17. M2*12 沉头内六角螺丝 | x5 |
| M2*12 countersunk hex screw | |
| 18. M2*10 沉头内六角螺丝 | x3 |
| M2*10 countersunk hex screw | |
| 19. M2*16 内六角螺丝 | x5 |
| M2*16 hex screw | |
| 20. M1.6*10 杯头内六角螺丝 | x5 |
| M1.6*10 socket head cap | |
| 21. M2*8 内六角螺丝 | x5 |
| M2*8 hex screw | |
| 22. M2 防松自紧螺母 | x7 |
| M2 lock nut | |
| 23. M2*3 沉头内六角螺丝 | x5 |
| M2*3 countersunk hex screw | |

(附赠)/(Additional parts)

- | | |
|-----------------------------|----|
| 1. 模拟摄像头固定侧板 | x2 |
| Analog camera side plate | |
| 2. M2*5 沉头内六角螺丝 | x5 |
| M2*5 countersunk hex screw | |
| 3. M2*5 内六角螺丝 | x5 |
| M2*5 hex screw | |
| 4. 电源线+插头 | x1 |
| Power cable + plug | |
| 5. 集线管 | x4 |
| Motor wire protecto | |
| 6. 15*180 超纤皮电池扎带 | x1 |
| 15*180 Battery strap | |
| 7. 15*200 超纤皮电池扎带 | x1 |
| 15*200 Battery strap | |
| 8. 电池硅胶防滑垫 | x2 |
| Battery pad | |
| 9. 自锁尼龙扎带 | x6 |
| Self-locking nylon zip ties | |
| 10. 通用贴纸 | x1 |
| Sticker | |

